



GM Service Bulletins and Recalls 1997 - 2003

Corvette C5 Kaufberatung

Seite 1

Die Datenbank von »Corvette Action Center« liefert eine Fülle von Service-Informationen zu allen Corvette-Modellen unter der Internet-Präsenz

<http://www.corvetteactioncenter.com/kb/category.php?catId=6>

Stand: 7. September 2003

Body Parts and Trim

1997-1998	SB	Discoloration or Staining of Plenum (Cowl) Air Inlet Screen
1997-1998	SB	Front Fender to Door Fit/Appearance (Install Retainer)
1997-1998	SB	Hiss Type Noise Coming From Weatherstrip When Closing
1997-1998	SB	Loose Lower Front Fascia Valence Panels
1997-1998	SB	Muffled Clatter Type Noise Coming From Center of Passenger Compartment
1997-1998	SB	Waterleak Above Door Glass (Reseal Blowout Clip)
1997-1999	SB	Door Handles on White Painted Cars Turning Yellow
1997-1999	SB	Loose or Missing Headlamp Door Bezel Plug
1997-2002	SB	General Waterleak Guide
1997	SB	Hatch Will Not Pop Up When Activated in Cold Weather
1997	SB	Water Drips into Rear Compartment After Hatch/Glass Has Been Opened
1998	SB	Clicking Noise Coming From Folding Top (Convertible only)
1998	SB	Tonneau Cover Makes Noise When Going Over Bumps (Convertible only)
1998-2000	SB	Window Motor Noisy/Inoperative
1998-2001	SB	Paint Wear Through at Fifth Bow (Replace Seal)
1998-2001	SB	Squeak From Rear of Convertible Top (Replace Protector Assembly)
1998-2003	SB	Prevention of Convertible Top From Rubbing Against the Paint Behind the Plastic Strip (Convertible only)
1998-2003	SB	Trunk Door on Convertible Won't Open All The Way (Convertible only)
1999-2001	SB	Windnoise Around B-Pillar (Add Sealer)
1999	SB	Left Fuel Tank to Underbody Contact/Rattle Noise
2000	SB	Left Headlamp Door Does Not Stay Closed
2003	SB	Deck Lid Not Flush With Left Hand Quarter Panel (Install Struts, Replace Right Deck Lid Hinge)

Chassis and Suspension

1997-2002	SB	SMU - Revised Side Cover and Gasket Replacement (RH)/Differential Carrier Cover and Seal Replacement
1999-2000	SB	SMU - Deletion of Variable Effort Steering Description

SB = Service Bulletin · R = Recall · PC = Product Campaign · Info = Technical Information

© 2000-2003 Corvette Action Center <http://www.corvetteactioncenter.com>

General Motors, GM, das GM-Emblem, Chevrolet, das Chevrolet-Emblem, Corvette, das Corvette-Emblem und ZR-1 sind eingetragene Markenzeichen und Chevy ist eine Marke der General Motors Corporation, Detroit, USA. Alle anderen Marken sind Eigentum ihrer jeweiligen Inhaber. Alle Angaben ohne Gewähr.



GM Service Bulletins and Recalls 1997 - 2003

Corvette C5 Kaufberatung

Seite 2

Electrical and Ignition

1997-2003	Info	PCM Reprogramming and Data Line Diagnosis using J 44236-A
1998-2000	SB	Electronic Steering Column Lock May Refuse to Operate - DIC Service Message Displayed
1997-1998	SB	Fuel Pump Noise Coming From Fuel Pump/Tank (Replace Fuel Pump Assembly)
1997-1998	SB	Inoperative Remote Keyless Entry System and/or Tire Pressure Monitor System
1997-1998	SB	Remote Keyless Entry System (RKE) and/or Low Tire Pressure Monitoring System Inoperative
1997-1999	SB	Chime Sounds When Key is Removed from Ignition
1997-1999	SB	No Start Condition, Non-Functional PCM After Reprogramming
1997-2000	Info	Diagnostic Trouble Codes
1997-2000	SB	Inaccurate/Erratic Fuel Level Gauge Readings
1997-2003	Info	Headlamp Actuator Replacement Procedure
1997-2003	Info	Resetting the Engine Oil Life Monitor
1997-2003	SB	Misfire DTCs and Catalytic Converter Damage Due to Installation of Alarm Systems
1997	PC	PCM Calibration Reflash
1997	SB	Erratic Fuel Gauge Readings
1997	SB	Various Driveability Issues (Repair/Secure Wire Harness at PCM)
1998	SB	Rear Window Defogger Inoperative (Convertible only)
1998-2000	R	Electronic Column Lock
1999-2002	SB	Erratic Fuel Gauge Reading (Reprogram the PCM)
1999	SB	Hesitation, Sag, Stumble and/or Backfire on Acceleration (Reprogram PCM)
2000	SB	Power Antenna Not Working Properly or is Completely Inoperative
2000	SB	Tech - Left Headlamp Door Does Not Stay Closed
2001	SB	Traction Control/Handling Lamp On
2002	SB	Erratic Fuel Gauge Reading (Reprogram the PCM)

Exhaust System

1993-1998	SB	Paint Peeling From Muffler
1997-1998	SB	Exhaust Muffler Insulator Rumble Noise
2000	SB	Exhaust Boom at 1500 RPM

Interior Parts and Trim

1997-1999	SB	Premature Wear of Leather Material on Bucket Seatback Bolster
1997-1999	SB	SMU - Revised Seatback Cover Removal Procedure
1997-1999	SB	Squeak Type Noise From Leather Shift Boot when Shifting Gears
1997-2000	R	Lap Belt Webbing Twisted
1997-2002	SB	Door Rattle with Moderate to High Audio System Volume
1997-2002	SB	Driver Seat Movement During Acceleration and Braking (Replace Adjuster Assembly)
1998-2000	SB	Window Motor Noisy/Inoperative

SB = Service Bulletin · R = Recall · PC = Product Campaign · Info = Technical Information

© 2000-2003 Corvette Action Center <http://www.corvetteactioncenter.com>

General Motors, GM, das GM-Emblem, Chevrolet, das Chevrolet-Emblem, Corvette, das Corvette-Emblem und ZR-1 sind eingetragene Markenzeichen und Chevy ist eine Marke der General Motors Corporation, Detroit, USA. Alle anderen Marken sind Eigentum ihrer jeweiligen Inhaber. Alle Angaben ohne Gewähr.



GM Service Bulletins and Recalls 1997 - 2003

Corvette C5 Kaufberatung

Seite 3

AC, Heating and Ventilation

- 1997-2003 SB HVAC Controls Intermittently Inoperative or Improperly Responding (Reset HVAC Controller)
- 1997 SB Blower Motor - Run on When Ignition is Off

Brakes

- 1995-2002 SB Warranty Admin. - Brake Rotor Warranty Service Procedure
- 2001-2002 SB Yellow Traction Control/Handling Lamp On and Driver Info Center Displays Service Hndlg.
- 2001 SB Incomplete Brake Pedal Return

Clutch and Transmission

- 1990-2003 SB Info - Diagnosis of Cracked or Broken Transmission Case
- 1996-1999 SB No Reverse, Second Gear, or Fourth Gear
- 1996-2000 SB Harsh 1-2 Upshift, SES, MIL, or CEL Illuminated, DTC P1870 Set
- 1997-2001 SB Park/Neutral Position Switch Connector Cannot Be Removed
- 1997-2002 SB Automatic Transmission Service Procedure Changes
- 1998-1999 SB Tech - Service Engine Soon (SES) Light Illuminates (Repl Switch Assy)
- 1999-2002 SB DTC P0757 Set, SES Lamp Illuminated, Poor Performance of Transmission, Transmission Slipping

Engine - Mechanical

- 1997-1998 SB Belt Rumble Noise at Low Idle Speeds
- 1997-1998 SB Reduced Engine Power Message Along With Partic. Powertrain
- 1997-1999 SB Accessory Drive Squeak (Replace Idler Pulley)
- 1997-1999 SB Engine Low Coolant Light Comes On (Inspect Rad. Surge Tank, Replace/Reposition)
- 1997-2000 SB Intermittent Accessory Drive Rumble During Garage Shift
- 1998-2002 SB Audible Spark Knock (Detonation), MIL Illuminated, DTC P0332 Set
- 1998-2002 SB Needle Bearings Found In Oil Pan (Replace Rocker Arms)
- 1999-2002 SB Higher Than Expected Oil Consumption
- 2001-2002 SB SMU - Revised DTC P1221
- 2001-2003 SB Engine Knock or Lifter Noise
- 2001 R **Product Emission Recall Uncertified Calibration**
- 2001 SB Lack of Power Following a Wide Open Throttle 4-2 or 3-2 Downshift and Subsequent 2-3 Upshift
- 2001 SB Whistle Noise From Intake Manifold/Throttle Body (Replace Intake Manifold)

Frame

- 1997-2003 Info [Corvette Crossmember Design and Manufacturing](#)

SB = Service Bulletin · R = Recall · PC = Product Campaign · Info = Technical Information

© 2000-2003 Corvette Action Center <http://www.corvetteactioncenter.com>

General Motors, GM, das GM-Emblem, Chevrolet, das Chevrolet-Emblem, Corvette, das Corvette-Emblem und ZR-1 sind eingetragene Markenzeichen und Chevy ist eine Marke der General Motors Corporation, Detroit, USA. Alle anderen Marken sind Eigentum ihrer jeweiligen Inhaber. Alle Angaben ohne Gewähr.



GM Service Bulletins and Recalls 1997 - 2003

Corvette C5 Kaufberatung

Seite 4

Tires and Wheels

1997-2003	SB	Info - Tire Pressure Monitoring System (TPMS) Grommet/Seal Availability
1997-1998	SB	Remote Keyless Entry System (RKE) and/or Low Tire Pressure Monitoring System Inoperative
1997-1999:		Wheel Touch-Up Paint
1997-2001	SB	Info - Wheel Pressure Sensors Unable to be Reprogrammed after Tire Replacement
2000	SB	Low Tire Pressure Message on DIC, Slow Air Loss
2001	Info	Proper Tire Pressure
2003	Info	Recommended Wheel Nut/Bolt Torque Specifications
	Info	Refinishing Aluminum Wheels
	Info	C5 Corvette EMT Run-Flat Tire Servicing

SB = Service Bulletin · R = Recall · PC = Product Campaign · Info = Technical Information

© 2000-2003 Corvette Action Center <http://www.corvetteactioncenter.com>

General Motors, GM, das GM-Emblem, Chevrolet, das Chevrolet-Emblem, Corvette, das Corvette-Emblem und ZR-1 sind eingetragene Markenzeichen und Chevy ist eine Marke der General Motors Corporation, Detroit, USA. Alle anderen Marken sind Eigentum ihrer jeweiligen Inhaber. Alle Angaben ohne Gewähr.